

ALT013 Alternator Skoda VW Polo Golf V Lupo 1.0 1.4


Katalog CA1750 CA1750IR CA 1750 A13VI241 2542294

028903029M CA1567 CA1567IR CA 1567 CA1568 CA1568IR

CA 1568 0124315007 SG8B017 2542279 037903025N

037903025G

Model	Pojemnosť	Od roku	Do roku
Seat Arosa	1.0	05.1997	07.2000
Seat Cordoba	1.0	06.1999	10.2002
Seat Cordoba	1.4 16V	10.2002	
Seat Cordoba	1.6	02.2003	
Seat Ibiza	1.0	05.1999	
Seat Ibiza	1.4 16V	02.2002	
Seat Ibiza	1.6	02.2003	
Skoda Fabia	1.4	03.2007	
Skoda Fabia	1.4 16V	09.2000	05.2004
Skoda Octavia	1.4	04.1999	
VW Fox	1.4	04.2005	
VW Golf V	1.4	06.2007	
VW Golf V	1.4 16V	05.2006	
VW Lupo	1.0	10.1998	07.2005
VW Polo	1.0	07.1998	09.2001
VW Polo	1.4	12.1998	04.2002
VW Polo	1.4 16V	06.2000	



Cena 4389,- Kč